Scenario Worksheet

Practice and Scenario Description:

| Practice and Scenario Description: | | |
|------------------------------------|--|---|
| Information Type | Data | |
| Region | Delta States | |
| State | Louisiana | |
| Discipline Group | Agricultural Engineering | |
| Practice Code/Name | 374 - Farmstead Energy Improvemen | nt |
| Scenario ID | 14 | |
| Scenario Name | Heating - Radiant Tube | |
| Scenario Description | re-plumb gas lines, cables and wench sy heating systems can include radiant bro brood heaters with 6 radiant tube heate Inefficient heat distribution equipment, | oultry house with Radiant Tube Heaters. Replacement will require the materials and labor to remove existing heating system, stem to retrofit new radiant tube heaters, and miscellaneous items to complete the installation. Alternate acceptable radiant oders and quad radiant systems as evidenced by the energy audit. The typical scenario consists of the replacement of 28 ers. such as conventional "pancake" brood heaters. The Pancake brooder, mounted at a low installation height, primarily warms perimeter at desired temperatures around each brooder. A large number of brooders are required to cover a significant |
| Before Practice Situation | * | ir naturally rises it loses effectiveness for poultry on the ground. |
| After Practice Situation | open fire). Air temperature is of relative above the floor level. This height extend radiant heat zone heats over twice that Farmstead Energy Improvement. The re | on of a more efficient heater. Radiant tube heaters primarily warm objects within a direct line of sight (similar to the sun or an ity little importance for a radiant heating systems to be effective. As a result, radiant sytems are typically installed 5' or more is the distribution of the radiant heat over a larger area than is possible with pancake style heaters. A roughly 16' diameter of a convential pancake brooder. Associated practices/activities may include: 122-AgEMP - HQ, and other activities within 374- source concern is inefficient use of energy in the farm operation which increases dependence on nerneewable energy mproved energy efficiency. Any improvements are based on a Type 2 energy audit meeting the requirements of ASABE S612. |
| Scenario Feature Measure | Radiant Heating Capacity | |
| Scenario Unit | 1000 BTU/Hour | |
| Scenario Typical Size | 875 | <u> </u> |

Cost Summary:

| Cost Category | Scenario Cost | Scenario Cost/Unit | | |
|------------------------------------|---------------|--------------------|--|--|
| Materials | \$8,569.12 | \$9.79 | | |
| Equipment/Installation | \$0.00 | \$0.00 | | |
| Labor | \$429.12 | \$0.49 | | |
| Mobilization | \$25.75 | \$0.03 | | |
| Acquisition of Technical Knowledge | \$0.00 | \$0.00 | | |
| Foregone Income | \$0.00 | \$0.00 | | |
| Total | \$9,023.99 | \$10.31 | | |

Cost Details:

| | | | | | 5 · (A) ··· | | |
|---------------|--------------|-----------------------------|--|------|-----------------|----------|------------|
| Cost Category | Component ID | | | Unit | Price (\$/unit) | Quantity | Cost |
| | | | Radiant tube heater rated at 125000 | | | | |
| Materials | 1163 | Heater, radiant tube | BTU/hour. Materials only. | Each | \$1,224.16 | 7 | \$8,569.12 |
| | | | | | | | |
| | | | Labor requiring a high level skill set: Includes | | | | |
| | | | carpenters, welders, electricians, conservation | | | | |
| | | | professionals involved with data collection, | | | | |
| Labor | 230 | Skilled Labor | monitoring, and or record keeping, etc. | Hour | \$26.82 | 16 | \$429.12 |
| | | | | | | | |
| | | | Mobilization of skilled labor: Includes | | | | |
| | | | carpenters, welders, electricians, conservation | | | | |
| | | | professionals involved with data collection, | | | | |
| Mobilization | 1141 | Mobilization, Skilled labor | monitoring, and or record keeping, etc. | Hour | \$25.75 | 1 | \$25.75 |